

Report
on the
Technical Inquiry
into the causes of
Breaches in river bunds
in Sind
steps required [&] to minimise
the danger of recurrence

by
C. C. Inglis

1943

A REPORT

ON THE

TECHNICAL INQUIRY INTO THE CAUSES OF BREACHES IN RIVER
BUNDS IN SIND AND STEPS REQUIRED TO MINIMISE THE
DANGER OF A RECURRENCE.

By

C. C. Inglis, C. I. E., B. A. I., M. Inst. C. E., M. Am. Soc., C. E., Director, Central
Irrigation and Hydrodynamic Research Station, Poona.

KARACHI
PRINTED AT THE GOVERNMENT PRESS
1943

INDEX

to the Report on the Technical Inquiry into the causes of Breaches in river bunds in Sind and steps required to minimise the danger of a recurrence, by C. C. Inglis, C.I.E., B.A.I., M. Inst. C.E., M. Am. Soc. C.E., Director, Central Irrigation and Hydrodynamic Research Station.

<i>Photos.</i>	<i>Pages.</i>
1. Breach No. 2—Mahomedabagh Loop.
2. Breach across North Western Canal above Ruk Regulator
3. Flood round Bubak village
4. Flood round Khairpur Nathanshah village.
5. Right bank erosion near N.-W. Railway
6. River at Sukkur Gorge and upstream in 1938 before embayment developed
Part I. Synopsis	I
Part II. Areas flooded during 1942 flood season	ib
Part III. Historical Review of steps taken by Sind Government to collect data in connection with the Indus and to control it in its passage through Sind	ib
Part IV. The causes of floods in Sind	4
Part V. Technical analysis of available data regarding water levels in the past and to be expected in future	6
Part VI. Conclusions and recommendations	II
Appendix I Suggestions for additions to and alterations in the Bund Manual	13
Appendix II One method of closing a river breach	16
Appendix III (a) Statement of breaches from 1930 onwards	18
Appendix III (b) Statement of breaches prior to 1930.	19
 <i>Figures.</i>	
1. Index plan of Sind showing canals, railways, embankments, rain and river gauges
2. Index plan showing areas flooded by Right Bank breaches, 1942
3. Indus Bulletin
4. Sketch showing 'sag' of cable of cable-suspended current-meter
5/1-7 Plan showing maximum swing of deep channel of Indus and existing and abandoned river bunds, with dates of construction where known
6. Showing contours of the whole of Sind (except Khairpur)
7. Top levels of the Sukkur-Begari Bund at mile 0-33 in 1929, 33, 35 and 42
8. Top levels of Kasimpur-Nabishah Bund at miles 0 to 22/6 in 1929, 33, 35 and 42
9. Graph showing maximum and minimum water levels at Bukkur from 1848 to 1942
10. Graph showing specific discharge gauges at Bachalshah from 1919 to 1942
11. Departure of specific-discharge gauge of each year compared with departures of average Abkalani discharge (June to September) of previous year. Departures are from 5 years moving average trend
12/1-3 Water levels at Gauge sites above Barrage from Bachalshah to Machka from 1922-42
13. Chart showing relation between discharge and charge of silt at Bukkur from 1913-30 and from 1930-42.
14. Chart showing time trends in discharge and average charge per cft. at Sukkur and Kotri from 1913-30 and 1930-42